Test Report issued under the responsibility of:

TEST REPORT
IEC 60034-1
Rotating Electrical Machines – Part 1: Rating and Performance

Report Number. .....:	**4789789586.2**
Date of issue .....:	**2021-08-31**
Total number of pages.....	**45**
Name of Testing Laboratory preparing the Report.....:	**Hiwin Mikrosystem Corp.**
Applicant's name .....:	**Hiwin Mikrosystem Corp.**
Address .....:	**6 Jingke Central Rd Taichung Precision Machinery Park Taichung, 40852 TW**
Test specification:	
Standard.....:	IEC 60034-1:2017, (Edition 13.0)
Test procedure .....:	Informative Test Report
Non-standard test method .....:	N/A
Test Report Form No. .....:	IEC60034_1_2017_05
Test Report Form(s) Originator ....:	UL
TRF version.....:	May 2019

General disclaimer:

The test results presented in this report relate only to the object tested.
This report shall not be reproduced, except in full, without the written approval of the Issuing Testing Laboratory.
The authenticity of this Test Report and its contents can be verified by contacting the Issuing Test Laboratory, responsible for this Test Report.

Copyright © 2019 UL LLC

Only those products bearing the UL Mark should be considered as being covered by UL.

Test item description .....:	Torque Motor
Trade Mark .....:	HIWIN HIWIN MIKROSYSTEM or HIWIN 大銀微系統
Manufacturer.....:	Hiwin Mikrosystem Corp.
Model/Type reference .....:	TM-2-13-LA0, TM-2-13-SA0, TM-2-15-LA0, TM-2-15-SA0, TM-2-17-LA0, TM-2-17-SA0, TM-2-1A-LA0, TM-2-1A-SA0, TM-2-1F-LA0, TM-2-1F-SA0, TM-2-13-PA0, TM-2-15-PA0, TM-2-17-PA0, TM-2-17-PB0, TM-2-1A-PA0, TM-2-1A-PB0, TM-2-1F-PA0, TM-2-1F-PB0, TM-2-23-PA0, TM-2-23-PB0, TM-2-25-PA0, TM-2-25-PB0, TM-2-27-PA0, TM-2-27-PB0, TM-2-2A-PA0, TM-2-2A-PB0, TM-2-2F-PA0, TM-2-2F-PB0, TM-2-23-LA0, TM-2-23-SA0, TM-2-25-LA0, TM-2-25-SA0, TM-2-27-LA0, TM-2-27-SA0, TM-2-2A-LA0, TM-2-2A-SA0, TM-2-2F-LA0, TM-2-2F-SA0, TM-2-43-LA0, TM-2-43-SA0, TM-2-45-LA0, TM-2-45-SA0, TM-2-47-LA0, TM-2-47-SA0, TM-2-4A-SA0, TM-2-4A-PB0, TM-2-4F-PA0, TM-2-4F-PB0, TM-2-43-PA0, TM-2-43-PB0, TM-2-45-PA0, TM-2-45-PB0, TM-2-47-PA0, TM-2-47-PB0, TM-2-4A-LA0, TM-2-4A-PA0, TM-2-4F-LA0, TM-2-4F-SA0, TM-2-73-LB0, TM-2-73-PB0, TM-2-75-PB0, TM-2-75-SB0, TM-2-77-PB0, TM-2-77-SB0, TM-2-7A-PB0, TM-2-7A-SB0, TM-2-7F-PB0, TM-2-7F-SB0, TM-2-73-LA0, TM-2-73-SB0, TM-2-75-LA0, TM-2-75-LB0, TM-2-77-LA0, TM-2-77-LB0, TM-2-7A-LB0, TM-2-7A-LD0, TM-2-7F-LB0, TM-2-7F-LD0, TM-2-A3-PB0, TM-2-A3-PC0, TM-2-A5-PB0, TM-2-A5-PC0, TM-2-A7-PC0, TM-2-A7-PF0, TM-2-AA-PC0, TM-2-AA-PF0, TM-2-AF-PC0, TM-2-AF-PF0, TM-2-A3-PA0, TM-2-A5-PA0, TM-2-A7-PA0, TM-2-A7-PB0, TM-2-A7-SC0, TM-2-AA-PB0, TM-2-AA-SC0, TM-2-AF-PB0, TM-2-AF-SC0, TM-2-AH-PC0, TM-2-D3-SB0, TM-2-D3-SD0, TM-2-D5-SB0, TM-2-D5-SD0, TM-2-D7-SB0, TM-2-D7-SD0, TM-2-DA-SB0, TM-2-DA-SD0, TM-2-DF-SB0, TM-2-DF-SD0, TM-2-D3-SA0, TM-2-D3-SH0, TM-2-D5-SA0, TM-2-D5-SH0, TM-2-D7-SA0, TM-2-D7-SH0, TM-2-DA-SA0, TM-2-DA-SH0, TM-2-DF-SH0, TM-2-G3-SB0, TM-2-G3-SD0, TM-2-G5-SB0, TM-2-G5-SD0, TM-2-G7-SB0, TM-2-G7-SD0, TM-2-GA-SB0, TM-2-GA-SD0, TM-2-GF-SD0, TM-2-GF-SH0, TM-2-G5-SA0, TM-2-G5-PD0, TM-2-G5-SH0, TM-2-G7-SA0, TM-2-G7-PD0, TM-2-G7-SH0, TM-2-GA-SA0, TM-2-GA-PD0, TM-2-GA-SH0, TM-2-GF-SB0, TM-2-GF-PD0, IM-2-23-PA0, IM-2-23-PB0, IM-2-25-PA0, IM-2-25-PB0, IM-2-27-PA0, IM-2-27-PB0, IM-2-2A-PB0, IM-2-2A-PD0, IM-2-2F-PB0, IM-2-2F-PD0, IM-2-43-LA0, IM-2-43-SA0, IM-2-45-LA0, IM-2-45-SA0, IM-2-47-SA0, IM-2-47-SB0, IM-2-4A-SA0, IM-2-4A-SB0, IM-2-4F-SA0, IM-2-4F-SB0, IM-2-43-SB0, IM-2-45-SB0, IM-2-73-SA0, IM-2-73-SB0, IM-2-75-SB0, IM-2-75-SD0, IM-2-77-SB0, IM-2-77-SD0, IM-2-7A-SB0, IM-2-7A-SD0, IM-2-7F-SD0, IM-2-7F-WD0, IM-2-7A-WD0, IM-2-A3-PB0, IM-2-A3-PC0, IM-2-A5-PC0, IM-2-A5-PF0, IM-2-A7-PC0, IM-2-A7-PF0, IM-2-AA-PC0, IM-2-AA-PF0, IM-2-AF-PF0, IM-2-AF-SF0, IM-2-A5-PB0, IM-2-AF-PC0, IM-2-G5-SB0, IM-2-G5-SD0, IM-2-G7-SB0, IM-2-G7-SD0, IM-2-GA-SB0, IM-2-GA-SD0, IM-2-GF-SD0, IM-2-GF-SH0, IM-2-G5-SH0, IM-2-G7-SH0, IM-2-GA-SH0.
Ratings .....:	Max. DC Bus: 750 V

Copyright © 2019 UL LLC

Only those products bearing the UL Mark should be considered as being covered by UL.