CERTIFICATE OF COMPLIANCE

Certificate Number	UL-US-2019872-0
Report Reference	E319289-20210324
Date	8-Apr-2021
Issued to:	HIWIN MIKROSYSTEM CORP 6 Jingke Central Rd Taichung Precision Machinery Park Taichung Taiwan 40852
This is to certify that representative samples of	NDMM2 - Incomplete Rotating Machines and Rotating Machine Parts - Component See Addendum Page for Product Designation(s).
	Have been investigated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.
Standard(s) for Safety:	UL 1004-1, 2nd Ed., Issue Date: 2012-09-19, Revision Date: 2020-11-05
Additional Information:	See the UL Online Certifications Directory at https://iq.ulprospector.com for additional information

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-2019872-0
Report Reference E319289-20210324
Date 8-Apr-2021

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
IM-2-23-PA0	Incomplete Motor Parts
IM-2-23-PB0	Incomplete Motor Parts
IM-2-25-PA0	Incomplete Motor Parts
IM-2-25-PB0	Incomplete Motor Parts
IM-2-27-PA0	Incomplete Motor Parts
IM-2-27-PB0	Incomplete Motor Parts
IM-2-2A-PB0	Incomplete Motor Parts
IM-2-2A-PD0	Incomplete Motor Parts
IM-2-2F-PB0	Incomplete Motor Parts
IM-2-2F-PD0	Incomplete Motor Parts
IM-2-43-LA0	Incomplete Motor Parts
IM-2-43-SA0	Incomplete Motor Parts
IM-2-43-SB0	Incomplete Motor Parts
IM-2-45-LA0	Incomplete Motor Parts
IM-2-45-SA0	Incomplete Motor Parts
IM-2-45-SB0	Incomplete Motor Parts
IM-2-47-SA0	Incomplete Motor Parts
IM-2-47-SB0	Incomplete Motor Parts
IM-2-4A-SA0	Incomplete Motor Parts
IM-2-4A-SB0	Incomplete Motor Parts
IM-2-4F-SA0	Incomplete Motor Parts
IM-2-4F-SB0	Incomplete Motor Parts
IM-2-73-SA0	Incomplete Motor Parts
IM-2-73-SB0	Incomplete Motor Parts
IM-2-75-SB0	Incomplete Motor Parts
IM-2-75-SD0	Incomplete Motor Parts
IM-2-77-SB0	Incomplete Motor Parts
IM-2-77-SD0	Incomplete Motor Parts
IM-2-7A-SB0	Incomplete Motor Parts
IM-2-7A-SD0	Incomplete Motor Parts
IM-2-7A-WD0	Incomplete Motor Parts
IM-2-7F-SD0	Incomplete Motor Parts
IM-2-7F-WD0	Incomplete Motor Parts
IM-2-A3-PB0	Incomplete Motor Parts
IM-2-A3-PC0	Incomplete Motor Parts
IM-2-A5-PB0	Incomplete Motor Parts
IM-2-A5-PC0	Incomplete Motor Parts

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-2019872-0
Report Reference E319289-20210324
Date 8-Apr-2021

IM-2-A5-PF0	Incomplete Motor Parts
IM-2-A7-PC0	Incomplete Motor Parts
IM-2-A7-PF0	Incomplete Motor Parts
IM-2-AA-PC0	Incomplete Motor Parts
IM-2-AA-PF0	Incomplete Motor Parts
IM-2-AF-PC0	Incomplete Motor Parts
IM-2-AF-PF0	Incomplete Motor Parts
IM-2-AF-SF0	Incomplete Motor Parts
IM-2-G5-SB0	Incomplete Motor Parts
IM-2-G5-SD0	Incomplete Motor Parts
IM-2-G5-SH0	Incomplete Motor Parts
IM-2-G7-SB0	Incomplete Motor Parts
IM-2-G7-SD0	Incomplete Motor Parts
IM-2-G7-SH0	Incomplete Motor Parts
IM-2-GA-SB0	Incomplete Motor Parts
IM-2-GA-SD0	Incomplete Motor Parts
IM-2-GA-SH0	Incomplete Motor Parts
IM-2-GF-SD0	Incomplete Motor Parts
IM-2-GF-SH0	Incomplete Motor Parts
TM-2-13-LA0	Incomplete Motor Parts
TM-2-13-PA0	Incomplete Motor Parts
TM-2-13-SA0	Incomplete Motor Parts
TM-2-15-LA0	Incomplete Motor Parts
TM-2-15-PA0	Incomplete Motor Parts
TM-2-15-SA0	Incomplete Motor Parts
TM-2-17-LA0	Incomplete Motor Parts
TM-2-17-PA0	Incomplete Motor Parts
TM-2-17-PB0	Incomplete Motor Parts
TM-2-17-SA0	Incomplete Motor Parts
TM-2-1A-LA0	Incomplete Motor Parts
TM-2-1A-PA0	Incomplete Motor Parts
TM-2-1A-PB0	Incomplete Motor Parts
TM-2-1A-SA0	Incomplete Motor Parts
TM-2-1F-LA0	Incomplete Motor Parts
TM-2-1F-PA0	Incomplete Motor Parts
TM-2-1F-PB0	Incomplete Motor Parts
TM-2-1F-SA0	Incomplete Motor Parts
TM-2-23-LA0	Incomplete Motor Parts
TM-2-23-PA0	Incomplete Motor Parts
TM-2-23-PB0	Incomplete Motor Parts
TM-2-23-SA0	Incomplete Motor Parts
TM-2-25-LA0	Incomplete Motor Parts
TM-2-25-PA0	Incomplete Motor Parts
TM-2-25-PB0	Incomplete Motor Parts
TM-2-25-SA0	Incomplete Motor Parts

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-2019872-0
Report Reference E319289-20210324
Date 8-Apr-2021

TM-2-27-LA0	Incomplete Motor Parts
TM-2-27-PA0	Incomplete Motor Parts
TM-2-27-PB0	Incomplete Motor Parts
TM-2-27-SA0	Incomplete Motor Parts
TM-2-2A-LA0	Incomplete Motor Parts
TM-2-2A-PA0	Incomplete Motor Parts
TM-2-2A-PB0	Incomplete Motor Parts
TM-2-2A-SA0	Incomplete Motor Parts
TM-2-2F-LA0	Incomplete Motor Parts
TM-2-2F-PA0	Incomplete Motor Parts
TM-2-2F-PB0	Incomplete Motor Parts
TM-2-2F-SA0	Incomplete Motor Parts
TM-2-43-LA0	Incomplete Motor Parts
TM-2-43-PA0	Incomplete Motor Parts
TM-2-43-PB0	Incomplete Motor Parts
TM-2-43-SA0	Incomplete Motor Parts
TM-2-45-LA0	Incomplete Motor Parts
TM-2-45-PA0	Incomplete Motor Parts
TM-2-45-PB0	Incomplete Motor Parts
TM-2-45-SA0	Incomplete Motor Parts
TM-2-47-LA0	Incomplete Motor Parts
TM-2-47-PA0	Incomplete Motor Parts
TM-2-47-PB0	Incomplete Motor Parts
TM-2-47-SA0	Incomplete Motor Parts
TM-2-4A-LA0	Incomplete Motor Parts
TM-2-4A-PA0	Incomplete Motor Parts
TM-2-4A-PB0	Incomplete Motor Parts
TM-2-4A-SA0	Incomplete Motor Parts
TM-2-4F-LA0	Incomplete Motor Parts
TM-2-4F-PA0	Incomplete Motor Parts
TM-2-4F-PB0	Incomplete Motor Parts
TM-2-4F-SA0	Incomplete Motor Parts
TM-2-73-LA0	Incomplete Motor Parts
TM-2-73-LB0	Incomplete Motor Parts
TM-2-73-PB0	Incomplete Motor Parts
TM-2-73-SB0	Incomplete Motor Parts
TM-2-75-LA0	Incomplete Motor Parts
TM-2-75-LB0	Incomplete Motor Parts
TM-2-75-PB0	Incomplete Motor Parts
TM-2-75-SB0	Incomplete Motor Parts
TM-2-77-LA0	Incomplete Motor Parts
TM-2-77-LB0	Incomplete Motor Parts
TM-2-77-PB0	Incomplete Motor Parts
TM-2-77-SB0	Incomplete Motor Parts
TM-2-7A-LB0	Incomplete Motor Parts

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-2019872-0
Report Reference E319289-20210324
Date 8-Apr-2021

TM-2-7A-LD0	Incomplete Motor Parts
TM-2-7A-PB0	Incomplete Motor Parts
TM-2-7A-SB0	Incomplete Motor Parts
TM-2-7F-LB0	Incomplete Motor Parts
TM-2-7F-LD0	Incomplete Motor Parts
TM-2-7F-PB0	Incomplete Motor Parts
TM-2-7F-SB0	Incomplete Motor Parts
TM-2-A3-PA0	Incomplete Motor Parts
TM-2-A3-PB0	Incomplete Motor Parts
TM-2-A3-PC0	Incomplete Motor Parts
TM-2-A5-PA0	Incomplete Motor Parts
TM-2-A5-PB0	Incomplete Motor Parts
TM-2-A5-PC0	Incomplete Motor Parts
TM-2-A7-PA0	Incomplete Motor Parts
TM-2-A7-PB0	Incomplete Motor Parts
TM-2-A7-PC0	Incomplete Motor Parts
TM-2-A7-PF0	Incomplete Motor Parts
TM-2-A7-SC0	Incomplete Motor Parts
TM-2-AA-PB0	Incomplete Motor Parts
TM-2-AA-PC0	Incomplete Motor Parts
TM-2-AA-PF0	Incomplete Motor Parts
TM-2-AA-SC0	Incomplete Motor Parts
TM-2-AF-PB0	Incomplete Motor Parts
TM-2-AF-PC0	Incomplete Motor Parts
TM-2-AF-PF0	Incomplete Motor Parts
TM-2-AF-SC0	Incomplete Motor Parts
TM-2-AH-PC0	Incomplete Motor Parts
TM-2-D3-SA0	Incomplete Motor Parts
TM-2-D3-SB0	Incomplete Motor Parts
TM-2-D3-SD0	Incomplete Motor Parts
TM-2-D3-SH0	Incomplete Motor Parts
TM-2-D5-SA0	Incomplete Motor Parts
TM-2-D5-SB0	Incomplete Motor Parts
TM-2-D5-SD0	Incomplete Motor Parts
TM-2-D5-SH0	Incomplete Motor Parts
TM-2-D7-SA0	Incomplete Motor Parts
TM-2-D7-SB0	Incomplete Motor Parts
TM-2-D7-SD0	Incomplete Motor Parts
TM-2-D7-SH0	Incomplete Motor Parts
TM-2-DA-SA0	Incomplete Motor Parts
TM-2-DA-SB0	Incomplete Motor Parts
TM-2-DA-SD0	Incomplete Motor Parts
TM-2-DA-SH0	Incomplete Motor Parts
TM-2-DF-SB0	Incomplete Motor Parts
TM-2-DF-SD0	Incomplete Motor Parts

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-2019872-0
Report Reference E319289-20210324
Date 8-Apr-2021

TM-2-DF-SH0	Incomplete Motor Parts
TM-2-G3-SB0	Incomplete Motor Parts
TM-2-G3-SD0	Incomplete Motor Parts
TM-2-G5-PD0	Incomplete Motor Parts
TM-2-G5-SA0	Incomplete Motor Parts
TM-2-G5-SB0	Incomplete Motor Parts
TM-2-G5-SD0	Incomplete Motor Parts
TM-2-G5-SH0	Incomplete Motor Parts
TM-2-G7-PD0	Incomplete Motor Parts
TM-2-G7-SA0	Incomplete Motor Parts
TM-2-G7-SB0	Incomplete Motor Parts
TM-2-G7-SD0	Incomplete Motor Parts
TM-2-G7-SH0	Incomplete Motor Parts
TM-2-GA-PD0	Incomplete Motor Parts
TM-2-GA-SA0	Incomplete Motor Parts
TM-2-GA-SB0	Incomplete Motor Parts
TM-2-GA-SD0	Incomplete Motor Parts
TM-2-GA-SH0	Incomplete Motor Parts
TM-2-GF-PD0	Incomplete Motor Parts
TM-2-GF-SB0	Incomplete Motor Parts
TM-2-GF-SD0	Incomplete Motor Parts
TM-2-GF-SH0	Incomplete Motor Parts

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

CERTIFICATE OF COMPLIANCE

Certificate Number	UL-CA-2016128-0
Report Reference	E319289-20210324
Date	8-Apr-2021

Issued to: HIWIN MIKROSYSTEM CORP
6 Jingke Central Rd
Taichung Precision Machinery Park Taichung
Taiwan 40852

This is to certify that representative samples of NDMM8 - Incomplete Rotating Machines and Rotating Machine Parts Certified for Canada - Component

See Addendum Page for Product Designation(s).

Have been investigated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.

Standard(s) for Safety: CSA C22.2 NO. 100, 7th Ed., Issue Date: 2014-07-01, Revision Date: 2017-04-01

Additional Information: See the UL Online Certifications Directory at https://iq.ulprospector.com for additional information

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-2016128-0
Report Reference E319289-20210324
Date 8-Apr-2021

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
IM-2-23-PA0	Incomplete Motor Parts
IM-2-23-PB0	Incomplete Motor Parts
IM-2-25-PA0	Incomplete Motor Parts
IM-2-25-PB0	Incomplete Motor Parts
IM-2-27-PA0	Incomplete Motor Parts
IM-2-27-PB0	Incomplete Motor Parts
IM-2-2A-PB0	Incomplete Motor Parts
IM-2-2A-PD0	Incomplete Motor Parts
IM-2-2F-PB0	Incomplete Motor Parts
IM-2-2F-PD0	Incomplete Motor Parts
IM-2-43-LA0	Incomplete Motor Parts
IM-2-43-SA0	Incomplete Motor Parts
IM-2-43-SB0	Incomplete Motor Parts
IM-2-45-LA0	Incomplete Motor Parts
IM-2-45-SA0	Incomplete Motor Parts
IM-2-45-SB0	Incomplete Motor Parts
IM-2-47-SA0	Incomplete Motor Parts
IM-2-47-SB0	Incomplete Motor Parts
IM-2-4A-SA0	Incomplete Motor Parts
IM-2-4A-SB0	Incomplete Motor Parts
IM-2-4F-SA0	Incomplete Motor Parts
IM-2-4F-SB0	Incomplete Motor Parts
IM-2-73-SA0	Incomplete Motor Parts
IM-2-73-SB0	Incomplete Motor Parts
IM-2-75-SB0	Incomplete Motor Parts
IM-2-75-SD0	Incomplete Motor Parts
IM-2-77-SB0	Incomplete Motor Parts
IM-2-77-SD0	Incomplete Motor Parts
IM-2-7A-SB0	Incomplete Motor Parts
IM-2-7A-SD0	Incomplete Motor Parts
IM-2-7A-WD0	Incomplete Motor Parts
IM-2-7F-SD0	Incomplete Motor Parts
IM-2-7F-WD0	Incomplete Motor Parts
IM-2-A3-PB0	Incomplete Motor Parts
IM-2-A3-PC0	Incomplete Motor Parts
IM-2-A5-PB0	Incomplete Motor Parts
IM-2-A5-PC0	Incomplete Motor Parts

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-2016128-0
Report Reference E319289-20210324
Date 8-Apr-2021

IM-2-A5-PF0	Incomplete Motor Parts
IM-2-A7-PC0	Incomplete Motor Parts
IM-2-A7-PF0	Incomplete Motor Parts
IM-2-AA-PC0	Incomplete Motor Parts
IM-2-AA-PF0	Incomplete Motor Parts
IM-2-AF-PC0	Incomplete Motor Parts
IM-2-AF-PF0	Incomplete Motor Parts
IM-2-AF-SF0	Incomplete Motor Parts
IM-2-G5-SB0	Incomplete Motor Parts
IM-2-G5-SD0	Incomplete Motor Parts
IM-2-G5-SH0	Incomplete Motor Parts
IM-2-G7-SB0	Incomplete Motor Parts
IM-2-G7-SD0	Incomplete Motor Parts
IM-2-G7-SH0	Incomplete Motor Parts
IM-2-GA-SB0	Incomplete Motor Parts
IM-2-GA-SD0	Incomplete Motor Parts
IM-2-GA-SH0	Incomplete Motor Parts
IM-2-GF-SD0	Incomplete Motor Parts
IM-2-GF-SH0	Incomplete Motor Parts
TM-2-13-LA0	Incomplete Motor Parts
TM-2-13-PA0	Incomplete Motor Parts
TM-2-13-SA0	Incomplete Motor Parts
TM-2-15-LA0	Incomplete Motor Parts
TM-2-15-PA0	Incomplete Motor Parts
TM-2-15-SA0	Incomplete Motor Parts
TM-2-17-LA0	Incomplete Motor Parts
TM-2-17-PA0	Incomplete Motor Parts
TM-2-17-PB0	Incomplete Motor Parts
TM-2-17-SA0	Incomplete Motor Parts
TM-2-1A-LA0	Incomplete Motor Parts
TM-2-1A-PA0	Incomplete Motor Parts
TM-2-1A-PB0	Incomplete Motor Parts
TM-2-1A-SA0	Incomplete Motor Parts
TM-2-1F-LA0	Incomplete Motor Parts
TM-2-1F-PA0	Incomplete Motor Parts
TM-2-1F-PB0	Incomplete Motor Parts
TM-2-1F-SA0	Incomplete Motor Parts
TM-2-23-LA0	Incomplete Motor Parts
TM-2-23-PA0	Incomplete Motor Parts
TM-2-23-PB0	Incomplete Motor Parts
TM-2-23-SA0	Incomplete Motor Parts
TM-2-25-LA0	Incomplete Motor Parts
TM-2-25-PA0	Incomplete Motor Parts
TM-2-25-PB0	Incomplete Motor Parts
TM-2-25-SA0	Incomplete Motor Parts

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-2016128-0
Report Reference E319289-20210324
Date 8-Apr-2021

TM-2-27-LA0	Incomplete Motor Parts
TM-2-27-PA0	Incomplete Motor Parts
TM-2-27-PB0	Incomplete Motor Parts
TM-2-27-SA0	Incomplete Motor Parts
TM-2-2A-LA0	Incomplete Motor Parts
TM-2-2A-PA0	Incomplete Motor Parts
TM-2-2A-PB0	Incomplete Motor Parts
TM-2-2A-SA0	Incomplete Motor Parts
TM-2-2F-LA0	Incomplete Motor Parts
TM-2-2F-PA0	Incomplete Motor Parts
TM-2-2F-PB0	Incomplete Motor Parts
TM-2-2F-SA0	Incomplete Motor Parts
TM-2-43-LA0	Incomplete Motor Parts
TM-2-43-PA0	Incomplete Motor Parts
TM-2-43-PB0	Incomplete Motor Parts
TM-2-43-SA0	Incomplete Motor Parts
TM-2-45-LA0	Incomplete Motor Parts
TM-2-45-PA0	Incomplete Motor Parts
TM-2-45-PB0	Incomplete Motor Parts
TM-2-45-SA0	Incomplete Motor Parts
TM-2-47-LA0	Incomplete Motor Parts
TM-2-47-PA0	Incomplete Motor Parts
TM-2-47-PB0	Incomplete Motor Parts
TM-2-47-SA0	Incomplete Motor Parts
TM-2-4A-LA0	Incomplete Motor Parts
TM-2-4A-PA0	Incomplete Motor Parts
TM-2-4A-PB0	Incomplete Motor Parts
TM-2-4A-SA0	Incomplete Motor Parts
TM-2-4F-LA0	Incomplete Motor Parts
TM-2-4F-PA0	Incomplete Motor Parts
TM-2-4F-PB0	Incomplete Motor Parts
TM-2-4F-SA0	Incomplete Motor Parts
TM-2-73-LA0	Incomplete Motor Parts
TM-2-73-LB0	Incomplete Motor Parts
TM-2-73-PB0	Incomplete Motor Parts
TM-2-73-SB0	Incomplete Motor Parts
TM-2-75-LA0	Incomplete Motor Parts
TM-2-75-LB0	Incomplete Motor Parts
TM-2-75-PB0	Incomplete Motor Parts
TM-2-75-SB0	Incomplete Motor Parts
TM-2-77-LA0	Incomplete Motor Parts
TM-2-77-LB0	Incomplete Motor Parts
TM-2-77-PB0	Incomplete Motor Parts
TM-2-77-SB0	Incomplete Motor Parts
TM-2-7A-LB0	Incomplete Motor Parts

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-2016128-0
Report Reference E319289-20210324
Date 8-Apr-2021

TM-2-7A-LD0	Incomplete Motor Parts
TM-2-7A-PB0	Incomplete Motor Parts
TM-2-7A-SB0	Incomplete Motor Parts
TM-2-7F-LB0	Incomplete Motor Parts
TM-2-7F-LD0	Incomplete Motor Parts
TM-2-7F-PB0	Incomplete Motor Parts
TM-2-7F-SB0	Incomplete Motor Parts
TM-2-A3-PA0	Incomplete Motor Parts
TM-2-A3-PB0	Incomplete Motor Parts
TM-2-A3-PC0	Incomplete Motor Parts
TM-2-A5-PA0	Incomplete Motor Parts
TM-2-A5-PB0	Incomplete Motor Parts
TM-2-A5-PC0	Incomplete Motor Parts
TM-2-A7-PA0	Incomplete Motor Parts
TM-2-A7-PB0	Incomplete Motor Parts
TM-2-A7-PC0	Incomplete Motor Parts
TM-2-A7-PF0	Incomplete Motor Parts
TM-2-A7-SC0	Incomplete Motor Parts
TM-2-AA-PB0	Incomplete Motor Parts
TM-2-AA-PC0	Incomplete Motor Parts
TM-2-AA-PF0	Incomplete Motor Parts
TM-2-AA-SC0	Incomplete Motor Parts
TM-2-AF-PB0	Incomplete Motor Parts
TM-2-AF-PC0	Incomplete Motor Parts
TM-2-AF-PF0	Incomplete Motor Parts
TM-2-AF-SC0	Incomplete Motor Parts
TM-2-AH-PC0	Incomplete Motor Parts
TM-2-D3-SA0	Incomplete Motor Parts
TM-2-D3-SB0	Incomplete Motor Parts
TM-2-D3-SD0	Incomplete Motor Parts
TM-2-D3-SH0	Incomplete Motor Parts
TM-2-D5-SA0	Incomplete Motor Parts
TM-2-D5-SB0	Incomplete Motor Parts
TM-2-D5-SD0	Incomplete Motor Parts
TM-2-D5-SH0	Incomplete Motor Parts
TM-2-D7-SA0	Incomplete Motor Parts
TM-2-D7-SB0	Incomplete Motor Parts
TM-2-D7-SD0	Incomplete Motor Parts
TM-2-D7-SH0	Incomplete Motor Parts
TM-2-DA-SA0	Incomplete Motor Parts
TM-2-DA-SB0	Incomplete Motor Parts
TM-2-DA-SD0	Incomplete Motor Parts
TM-2-DA-SH0	Incomplete Motor Parts
TM-2-DF-SB0	Incomplete Motor Parts
TM-2-DF-SD0	Incomplete Motor Parts

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-2016128-0
Report Reference E319289-20210324
Date 8-Apr-2021

TM-2-DF-SH0	Incomplete Motor Parts
TM-2-G3-SB0	Incomplete Motor Parts
TM-2-G3-SD0	Incomplete Motor Parts
TM-2-G5-PD0	Incomplete Motor Parts
TM-2-G5-SA0	Incomplete Motor Parts
TM-2-G5-SB0	Incomplete Motor Parts
TM-2-G5-SD0	Incomplete Motor Parts
TM-2-G5-SH0	Incomplete Motor Parts
TM-2-G7-PD0	Incomplete Motor Parts
TM-2-G7-SA0	Incomplete Motor Parts
TM-2-G7-SB0	Incomplete Motor Parts
TM-2-G7-SD0	Incomplete Motor Parts
TM-2-G7-SH0	Incomplete Motor Parts
TM-2-GA-PD0	Incomplete Motor Parts
TM-2-GA-SA0	Incomplete Motor Parts
TM-2-GA-SB0	Incomplete Motor Parts
TM-2-GA-SD0	Incomplete Motor Parts
TM-2-GA-SH0	Incomplete Motor Parts
TM-2-GF-PD0	Incomplete Motor Parts
TM-2-GF-SB0	Incomplete Motor Parts
TM-2-GF-SD0	Incomplete Motor Parts
TM-2-GF-SH0	Incomplete Motor Parts

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/